ENGINEERING DIVISION W/OSO422:GG

WSR-88D MODIFICATION NOTE 43 (For Electronics Technicians)

SUBJECT : Expansion of narrowband communications ports in

the RPG communications cabinet for connection of

AWIPS.

PURPOSE : To expand narrowband communication ports at

selected RPG sites.

EQUIPMENT AFFECTED : Radar Product Generation (RPG) Group.

PARTS REQUIRED : The following parts compose Kit A, for adding a

Dedicated Modem to an FSP RPG; Kit C, for adding a VME Narrowband Card; Kit D, for adding a Dedicated Modem to an LPP RPG; Kit F, for adding a Modem Expansion Rack; and Kit G, for

adding a Patch Panel.

Quantity in Kits: Verifying and labeling kits is suggested prior to initiating modification.

| Α | С | D | F | G | Nomenclature | Part Number | NSN |
|---|---|---|---|---|---------------------------|-------------|------------------|
| 1 | - | - | - | - | Cable Assembly | 1221203-530 | 5995-01-387-3817 |
| - | 1 | - | - | - | VME 4 to 1 Cable | 1222423-302 | 5995-01-417-4640 |
| - | 1 | - | - | - | VME Narrowband Board | 1222421-204 | 5998-01-397-8290 |
| 1 | - | 1 | - | - | Modem, Dedicated | 1219739-202 | 5895-01-377-7105 |
| 1 | - | 1 | - | - | Label, Cable (sheet) | SLSH-2015-5 | 7690-01-049-1770 |
| 2 | - | 2 | - | - | Arrester, electrical | COHP-150 | 5920-01-390-1340 |
| 1 | - | 1 | - | - | Tiewraps | MS3367-2-9 | 5975-00-156-3253 |
| - | - | 1 | - | - | Cable Assembly | 1222302-307 | 5995-01-407-2893 |
| - | - | - | 1 | - | Rack W/Power Supply | 80400 | 5975-01-389-4415 |
| - | - | - | 1 | - | Locator Plate, (A2) | 1214845-202 | 9905-01-417-1917 |
| - | - | - | - | 1 | Patch Panel, Dedicated | 1213826-201 | 5805-01-358-4488 |
| - | - | - | - | 1 | Cable Assy., (22/122 W22) | 1214790-304 | 5995-01-440-7556 |
| - | - | - | - | 1 | Cable Assy., (22/122 W21) | 1214789-307 | 5995-01-407-2894 |
| - | - | - | - | 1 | Locator Plate, (A13) | 1214845-213 | 9905-01-440-7558 |
| - | - | - | - | 1 | Cable Assy., (W230) | 1214868-303 | 5995-01-440-7552 |
| - | - | - | - | 8 | Screw | MS51958-61 | 5305-00-059-3657 |
| - | - | - | - | 8 | Washer | MS35338-138 | 5310-00-933-8120 |
| - | - | - | - | 8 | Washer | MS15795-808 | 5310-00-619-1148 |

MOD PROCUREMENT : Kits will be requisitioned by the Operational

Support Facility, Logistics Section, and shipped at

no cost to the site from the NLSC.

SPECIAL TOOLS AND TEST EQUIPMENT REQUIRED

None.

TIME REQUIRED : 4.0 staff-hours.

EFFECT ON OTHER INSTRUCTIONS

: None.

AUTHORIZATION STATEMENT : The authority for this modification is OSF ECP

F0009R03C1, "INSTALL ADDITIONAL

NARROWBAND PORTS ON WSR-88Ds FOR

ADVANCED WEATHER INTERACTIVE PROCESSING SYSTEM (AWIPS)".

VERIFICATION STATEMENT

This modification was successfully kit proofed at

Jacksonville, Florida, on July 8, 1997.

GENERAL

This modification expands narrowband communications ports to add AWIPS at selected sites. This will involve adding a combination of a Codex Modulus 21 modem expansion rack, Codex 3263 dedicated modems, Formation VME narrowband cards, and Datapatch RJ11-12-4 patch panels. This modification must be accomplished after Build 8.0 applications software is installed in order to activate the communication ports. Activating dedicated telephone service added under this modification is the responsibility of the requesting agency.

For additional information concerning this modification note, contact the Operational Support Facility, System Support Branch, Norman, Oklahoma; phone number: (405) 366-6540 ext. 3229.

PROCEDURE

See Attachments 1 (RPG Port Expansion Procedures), 2 (RPG Modem Test Procedures), and 3 (Application Software Changes to Expansion Ports at the RPG).

EFFECTIVITY

See Attachment 5.

EHB-6 Issuance 97-09 07/22/97

REPORTING MODIFICATION

Target date for completion of this modification is 60 days after receipt of modification note and parts. Report completed modification on WS Form A-26, Engineering Management Reporting System Maintenance Record, according to instructions in EHB-4, Part 2. Use reporting code RPG. Also, record the modification number in block 17(a) as "43" (see Attachment 6 for a completed sample of WS Form A-26). Record the NSN of the kits installed in block 13b and for each kit installed, record the corresponding part information:

| KIT | PART | Report in Block 18b | Report in Block 18c |
|-----|--|------------------------------------|---------------------|
| Α | Dedicated Modem 1219739-202 | Reference Designator/Slot Location | Serial Number |
| С | VME Narrowband Card 1222421-204 | Reference Designator/Slot Location | Serial Number |
| D | Dedicated Modem 1219739-202 | Reference Designator/Slot Location | Serial Number |
| F | Modem Expansion Rack Codex Modulus 21 | Reference Designator/Slot Location | Serial Number |
| G | Patch Panel Datapatch RJ11-12-4 | Reference Designator/Slot Location | Serial Number |

In addition, complete Attachment 4 and fax or mail to:

System Support Branch, Logistics Section Operational Support Facility 3200 Marshall Ave Suite 101 Norman, Oklahoma 73072-8028

Fax number (405) 366-6553

Or mail information to Kim Hare at:

khare@osf.noaa.gov

SignedJohn McNulty, Chief Engineering Division

SignedJames D. Belville, Director
Operational Support Facility

EHB-6 Issuance 97-